



Intertek

PROGRAM ADMINISTRATOR
DEPARTMENT ALECP
INTERTEK
3933 U.S. ROUTE 11
CORTLAND, NY 13045-0950

REVISION DATE: September 8, 2016

ORIGINAL ISSUE DATE: August 12, 2015

Recertification due: February 2022

An Activity Sponsored and Administered by
Intertek

ADB AIRFIELD SOLUTIONS, LLC.
977 GAHANNA PKWY
COLUMBUS, OH 43230

**AIRPORT LIGHTING
EQUIPMENT
CERTIFICATION PROGRAM**

**CERTIFICATE OF
CONFORMANCE**

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. The certification is not valid for a product modified with non-OEM replacement parts or non-production components.

L-804 – Runway Guard Unidirectional; yellow, flashing (AC 150/5345-46E)		
Manufacturer	Mode	Manufacturer's Catalog Number
ADB Airfield Solutions, LLC.	1	44A4744-1X11 (667)
	2	44A4744-2X12 (667); 44A4744-3X12 (667)

NOTE: (667) 48A0353

1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
2. Product tested and Report issued by: Intertek; ADB Airfield Solutions

(A) Report No: 101501625CRT-001;
101788382CRT-001; 113A0732; 102407542CRT-
001; 102678369CRT-001

(B) Date of Report: 2/2014; 7/2015; 11/2014; 5/2016;
8/2016

NOTE: PLEASE REVIEW, AND ADVISE
ADMINISTRATOR AT INTERTEK IMMEDIATELY
IF DATA, AS SHOWN, NEED TO BE
CORRECTED.

Approved for Certification by:

Jeremy N Downs, PE, Program Administrator

Date: September 8, 2016